

09/845,154

TCW
Cop



PATENT
Customer No. 22,852
Attorney Docket No. 07883.0033

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,854,467 B2)
Inventors: Peter Boekstegers)
Issue Date.: February 15, 2005)
For: METHODS AND DEVICES FOR)
DELIVERING A VENTRICULAR)
STENT)

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254 and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistakes identified in the appended Form PTO 1050 occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of Form PTO 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the corrections set forth on the Form PTO 1050 is earnestly requested.

U.S. Patent No. 6,854,467 B2
Attorney Docket No. 07883.0033
Request for Certificate of Correction - April 15, 2005

Please charge any required fees any required fees not included herewith to our
Deposit Account No. 06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: April 15, 2005
By: 
Michael W. Kim
Reg. No. 51,880

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. 6,854,467 B2

DATED: February 15, 2005

INVENTORS: Peter BOEKSTEGERS

It is hereby certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 46, column 16, line 21, "claim 43," should read --claim 45,--.

In claim 53, column 16, line 42, "piecing" should read --placing--.

In claim 74, column 18, line 29, "pas" should read --past--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue
Washington, D.C. 20001-4413

Patent No. 6,854,467 B2

No. of additional copies
@ .30¢ per page